

मंडल कार्यालय आदेश 09/2024

समस्त मुख्य लोको निरीक्षक
एवं मुख्य कू नियंत्रक, जोधपुर एवं मेड़तारोड
समस्त लोकोपायलट, लोकोपायलट शंटर एवम सहायक लोकोपायलट

विषय :- RTIS & CVVRS के कार्यरत अवस्था में होने बाबत

सन्दर्भ - Letter no NWR-HQ(ELECT(TR)/139/2020 Date 01.04.24

उपरोक्त विषय में संदर्भित पत्र अनुसार सभी मुख्य लोको निरीक्षको को निर्देश दिए जाते हैं कि अपने नामित व अन्य रनिंग स्टाफ को निम्न बिन्दुओं पर काउन्सलिंग करे तथा स्वयं भी फुटप्लेट के दौरान इसकी जाँच करे तथा अनुपालना रिपोर्ट मंडल कार्यालय में जमा करे।


1. इलेक्ट्रिक लोको को शेड/ट्रिप शेड से OUT करते समय RTIS तथा CVVRS की MCB का ऑन होना तथा उसके SYSTEM का कार्यशील होना सुनिश्चित करे यदि किसी कारणवश कार्यशील नहीं है तो इसकी सूचना शेड व TLC को देवे।
2. लोको का चार्ज लेते समय RTIS तथा CVVRS की सभी MCB का ON होना सुनिश्चित करे यदि OFF है तो इसकी सूचना TLC को देवे तथा ड्यूटी के दौरान OFF न करे।

प्रतिलिपि - मंडल रेल प्रबन्धक, सादर सूचनार्थ

अपर मंडल रेल प्रबन्धक, सादर सूचनार्थ

वरि.मंडल संरक्षा अधिकारी, सूचनार्थ

स.म.या.इंजी.(शक्ति), सूचनार्थ व आवश्यक कार्यवाही हेतु


वरी.मंडल यांत्रिक इंजी.(Enhm&P)
उ.प.रेलवे, जोधपुर

उत्तरपश्चिमरेलवे,
प्रधानकार्यालय, बिजलीविभाग,
जयपुर- 302017



North Western Railway
Headquarter Office,
Electrical Branch,
Jaipur -302017

NWR-HQ0ELCT(TR)/139 /2020

Dated :01.04.2024


Sr.DME/DSL/ABR & BGKT
Sr.DME/P/AII, BKN, JP & JU.

Sub.:-RTIS & CVVRS attention during maintenance.

In ref to above, all coaching locos are fitted with RTIS over IR. For effective monitoring of locomotives online and to assist in case of failure investigation and other incident analysis, it is essential that RTIS and CVVRS be operational in all locomotives.

Therefore it is advised to ensure below during schedule attention in sheds/trip sheds.

1. During the shed out of locomotives from Sheds/Trip sheds, it is ensured that RTIS and CVVRS MCB's must be in ON position & systems are in working order. In case RTIS or CVVRS are not operational in any locomotive for any reason, the concerned shed should be informed promptly.
2. It is ensure to download CVVRS & Event recorder data in sheds/trip sheds of all locomotives shed in.
3. It is also ensured that no locomotive should be shed out without implementing MS 497 guidelines regarding power supply to RTIS.


(Harish Sharma)
SEE/NWR
For CELE/NWR