

NORTH WESTERN RAILWAY

Divisional office
Jodhpur
Date 20.04.2026

L. No. 1AT/Safety/HQ SD-01/26

Safety Drive No.01/2026-27

Sr. DEN/Co.
All Sr. DEN

Sub: Special Safety Drive on disposal of unused/released P. Way materials.
Ref: (i) Railway Board's Letter No. 2024/संरक्षा (सिविल) /8/1/सलाह dated 15.04.26
(ii) NWR/HQ/Safety/SD/01/26, dated- 17.04.2026

Vide above reference, a Special Safety Drive for 15 days is to be launched with effect from 17.04.2026 to 01.05.2026 for disposal of unused/released P-Way materials. A case of hitting of running train by released materials stacked near tracks has come to notice. This seems to have occurred due to non-observance of rules for stacking and disposal of p-way material in block section and near tracks. Released material lying near running track must be removed as early as possible.

Hence it has been decided that a special safety drive for a period of 15 days may be launched to ensure that P-way material lying near tracks is stacked and disposed properly in accordance with the extant instructions. Inspections should be carried out on all sections paying attention to this aspect. This aspect can be reported by officials of all departments inspecting the section, as per the format below. Special emphasis is to be given to following aspects during the Drive:

- i. Material released from track renewal works should be removed from vicinity of running tracks within reasonable time and disposed of in accordance with extant instructions.
- ii. Till the time of their final disposal, released rails should be kept on cess, away from running rails.
- iii. Smaller isolated pieces of rails should be removed from worksites immediately after work and should be stored away from tracks so that any miscreant activity is prevented.

Appropriate follow up action should be taken on all deficiencies and irregularities noticed during the drive. The result of the drive should be sent to this office in following format by 02.05.2026. All officers and supervisors of Engineering departments should be mobilized to conduct this drive.

Date	Name of inspecting official	Designation of inspecting official	Division where inspection	Section	Detail of Deficiency	Action taken/ Compliance done

The Link of Google spread sheet is given below for entering the details of inspection & Compliance.

<https://docs.google.com/spreadsheets/d/17IfNoYcvFHpdwsOX2THFYMEHXzjVIZ92icB1f7ciQ/edit?usp=sharing>

January 20/4126
 Sr. Divisional Safety Officer
 North Western Railway
 Jodhpur

C/o- DRM, ADRM/JU- For kind information please.

No. NWR/HQ/Safety/SD/01/26

Headquarter Office

Jaipur

Date: 17.04.2026

Safety Drive No. 01/2026-27**PCE - NWR
DRMs-AII, BKN, JP & JU****Sub: Special Safety Drive on disposal of unused/released P. Way materials.****Ref: Railway Board's Letter No. 2024/संरक्षा (सिविल) /8/1/सलाह dated 15.04.26**

Vide above reference, a Special Safety Drive for 15 days is to be launched with effect from 17.04.2026 to 01.05.2026 for disposal of unused/released P-Way materials. A case of hitting of running train by released materials stacked near tracks has come to notice. This seems to have occurred due to non-observance of rules for stacking and disposal of p-way material in block section and near tracks. Released material lying near running track must be removed as early as possible.

Hence it has been decided that a special safety drive for a period of 15 days may be launched to ensure that P-way material lying near tracks is stacked and disposed properly in accordance with the extant instructions. Inspections should be carried out on all sections paying attention to this aspect. This aspect can be reported by officials of all departments inspecting the section, as per the format below. Special emphasis is to be given to following aspects during the Drive:

- i. Material released from track renewal works should be removed from vicinity of running tracks within reasonable time and disposed off in accordance with extant instructions.
- ii. Till the time of their final disposal, released rails should be kept on cess, away from running rails.
- iii. Smaller isolated pieces of rails should be removed from worksites immediately after work and should be stored away from tracks so that any miscreant activity is prevented.

Appropriate follow up action should be taken on all deficiencies and irregularities noticed during the drive. The result of the drive should be sent to this office in following format by 02.05.2026. All officers and supervisors of Engineering & Safety departments should be mobilized to conduct this drive. Officers from HQ should also be involved. Effective action must be taken on all deficiencies and irregularities noticed during the drive. Sr. DSOs should closely watch the quality of checks and critically analyse the shortcomings to identify systemic deficiency.

Date	Name of inspecting official	Designation of inspecting official	Division where inspection done	Section	Detail of Deficiency	Action taken / Compliance

The Link of Google spread sheet is given below for entering the details of inspection & Compliance.

<https://docs.google.com/spreadsheets/d/17IfNoYcvFHpdwsOX2THFYMEHXzjV-lZ92icB1f17ciQ/edit?usp=sharing>


17.04.2026

Manvendra Singh Raghav
Dy.CSO/Engg.

DA- As above

Copy to:- Secretary to GM for kind information of GM
Secretary to AGM for kind information of AGM
Sr. DSOs- AII, BKN, JP, JU- for necessary action and follow up.

Government of India (भारत सरकार)
Ministry of Railways (रेल मंत्रालय)
Railway Board (रेल्वे बोर्ड)

2024/संरक्षा(सिविल)/8/1/सलाह

नई दिल्ली, 15.04.2026

General Manager (महाप्रबंधक),
All Zonal Railways (सभी क्षेत्रीय रेल्वे),

Managing Director (प्रबंध निदेशक),
KRCL (कोंकण रेलवे कॉर्पोरेशन लिमिटेड) &
DFCCIL (डेडिकेटेड फ्रेट कॉरिडोर कॉरपोरेशन ऑफ इंडिया लिमिटेड),

Sub: Special Safety Drive on disposal of unused/released P.Way materials.

A case of hitting of running train by released materials stacked near tracks has come to notice. This seems to have occurred due to non-observance of rules for stacking and disposal of pway material in block section and near tracks. Released material lying near running track must be removed as early as possible.

Hence it has been decided that a special safety drive for a period of 15 days may be launched to ensure that P.way material lying near tracks is stacked and disposed properly in accordance with the extant instructions. Inspections should be carried out on all sections paying attention to this aspect. This aspect can be reported by officials of all departments inspecting the section, as per the format below.

Special emphasis should be given to following:

- i. Material released from track renewal works should be removed from vicinity of running tracks within reasonable time and disposed off in accordance with extant instructions.
- ii. Till the time of their final disposal, released rails should be kept on cess, away from running rails.
- iii. Smaller isolated pieces of rails should be removed from worksites immediately after work and should be stored away from tracks so that any miscreant activity is prevented.

1

Appropriate follow up action should be taken on all deficiencies and irregularities noticed during the drive. The result of the drive should be sent to board in following format by 04.05.2026 on the mail edsafetvcivil@gmail.com.

Zone	Division	Section	Number of locations where improperly stacked pway material detected	Remarks (if any)

CRS
15/4/26.

(RAHUL SRIVASTAVA)/(राहुल श्रीवास्तव)
Executive Director Safety (Civil)
कार्यकारी निदेशक संरक्षा(सिविल)
Railway Board/रेलवे बोर्ड

Copy to: PCSO's all Zonal Railways.